IDS Common Quality Clauses

manufacturer's name.

2) Material must be physically identified by permanent marking method with material type and heat lot number. Tag identification may only be used on material having 3/8" or less surface for marking.