



## Section 6 : QUALITY ASSURANCE CLAUSES / CQAR

---

### 610. Traceability Data (6/15/97).

Seller will maintain part traceability for each subassembly by completing the enclosed Item Traceability Record (ITR) form or a form of its choosing that records the same data. The ITR will be included in the Acceptance Data Package (ADP). If an ADP is not required, the ITR will be provided as a part of the end-item delivery. The ITR for each subassembly will, as a minimum, contain the following:

- (a) Drawing find number
- (b) Subassembly reference designation (EEE parts)
- (c) Part number
- (d) Description
- (e) Manufacturer's name and CAGE code
- (f) Traceability designator (lot/date code, batch/heat lot number)
- (g) Serial number (when required)
- (h) A list of the following electrical, electronic, electromechanical (EEE) parts:

Capacitors    Protective Devices

Connectors    Relays

Contacts      Resistors

Crystals      Switches

Diodes        Thermistors

Filters        Transistors

Inductors     Transformers

Microcircuits

- (i) A list of the following mechanical parts:

Bolts    O-Rings

Clamps    Pins

Gaskets    Screws

Inserts    Seals

Nuts      Springs