

Q812 General Quality Assurance Requirements - rev 3/6/01

The contractor shall be responsible for the safety and quality assurance of all contracted work. The Boeing Company Product Assurance Quality Engineering (PAQE) branch will monitor all work performed for satisfactory compliance with applicable standards, and verify that the work performed for satisfactory compliance with applicable standards, and verify that the work is being accomplished in accordance with the purchase order/contract requirements. The contractor shall not subcontract any work without prior approval of The Boeing Company. PAQE reserves the right to:

- 1) Inspect the contractor's facility to ensure the contractor has the capability, tools, equipment, and spare parts to perform the work specified in the purchase order/contract;
- 2) Audit the contractor's Quality Assurance Program to verify its compliance with purchase order/contract requirements;
- 3) Take photographs as deemed appropriate during the manufacturing, inspection, or testing process;
- 4) Inspect all work being performed under this contract at the contractor's facility, the contractor's sub-tier suppliers, or at Kennedy Space Center.