

**CODE 2A
COMPANY SOURCE INSPECTION
(IN PROCESS INSPECTION REQUIRED)**

Articles or services purchased hereunder will require in-process and final Buyer inspection prior to shipment from your plant. In-process inspection points shall be established by Procurement Quality Engineering for each part number during a post award conference.

When articles or services are ready for inspection, notify the Buyer's inspection representative and make available to the representative a copy of the related purchase order, applicable drawings, specifications, and changes thereto, related inspection and/or test equipment, and such other information as may be required to satisfactorily perform the Quality Assurance function required under this order.

For inspection services required by this order, contact:

Procurement Quality Assurance
Area Code (714) 762-3937 or
Fax (714) 762-0662 or
E-mail address: source.anaheim@west.boeing.com

When requesting source inspection, include the following information:

- a) Purchase order number
- b) Item number
- c) Part number
- d) Quantity of part to be inspected
- e) Date source inspection is required
- f) Contact name and phone no.