

Q949 Traceability - rev 10/1/01

(a) Raw Material. Seller will mark each individual item and applicable documentation (i.e. test report, shipping report, or certification) to show clear traceability to lot, heat lot, or batch number. Unless otherwise directed by this contract or the specification, when the size of the item does not permit marking of individual items, Seller will label each package or box furnished.

(b) Manufactured Goods. Seller will mark each item and applicable documentation (i.e. test reports, shipping reports, or certifications) to show clear traceability to the manufacturing lot or batch number. (Note: It is not necessary to provide traceability for the detail parts that make up the end item.) Unless otherwise directed by this contract or the specification, when the size of the item does not permit marking of individual items, Seller will label each package or box furnished.